

# Issue #5: Through-Hole Components

- Significant risk of insufficient hole fill
  - Can lead to single-sided architecture
  - Rectified through increasing solder pot temperature
- Single-sided
  - Shrinkage cracks found to have severe influence on time to failure
  - Will require new optical inspection criteria

